

# Griffin Creek Elementary School

Medford SD 549C

Jack\_sch23A

Building Type	County	
School	Jackson	
Street		
2430 Griffin Creek Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.29439	122.90757	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Griffin Creek Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Griffin Creek Elementary School

Jack\_sch23A

Enrollment 560	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1970
Total Area (square ft) 52530	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Plan Irregularity Primary Minor reentrant corner.			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Griffin Creek Elementary School

Medford SD 549C

Jack\_sch23B

Building Type	County	
School	Jackson	
Street		
2430 Griffin Creek Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.29425	122.90806	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Tertiary		0	0	0	0	0	0	0	0	0

Griffin Creek Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Griffin Creek Elementary School

Jack\_sch23B

Enrollment 560	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1970
Total Area (square ft) 52530	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Torsion: Eccentric Stiffness None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Plan Irregularity Primary west side is all wood			

# Griffin Creek Elementary School

Medford SD 549C

Jack\_sch23C

Building Type	County	
School	Jackson	
Street		
2430 Griffin Creek Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.29452	122.90814	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	1.6	-0.8	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Griffin Creek Elementary School

## Final RVS Score

Final Type	Final Score
W2	2.6

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Griffin Creek Elementary School

Jack\_sch23C

Enrollment 560	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1980
Total Area (square ft) 52530	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	

# Griffin Creek Elementary School

Medford SD 549C

Jack\_sch23D

Building Type	County	
School	Jackson	
Street		
2430 Griffin Creek Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.29467	122.90709	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Griffin Creek Elementary School

## Final RVS Score

Final Type	Final Score
W2	4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Griffin Creek Elementary School

Jack\_sch23D

Enrollment 560	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1950
Total Area (square ft) 52530	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Vertical Irregularity Primary also shows plan irregularity.		S Primary Structural Type	

# Griffin Creek Elementary School

Medford SD 549C

Jack\_sch23E

Building Type	County	
School	Jackson	
Street		
2430 Griffin Creek Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.29393	122.90733	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5

Griffin Creek Elementary School

**Final RVS Score**

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)
-------------



OregonGeology

# Griffin Creek Elementary School

Jack\_sch23E

Enrollment 560	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 52530	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W    General Site Masonry wall, vertical irregularity can also be seen.		SE    Plan Irregularity Primary	
		E    Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Griffin Creek Elementary School

Medford SD 549C

Jack\_sch23F

Building Type	County	
School	Jackson	
Street		
2430 Griffin Creek Rd		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.2939	122.90816	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Griffin Creek Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Griffin Creek Elementary School

Jack\_sch23F

Enrollment 560	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1990
Total Area (square ft) 52530	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	