

Hoover Elementary School

Medford SD 549C

Jack_sch24A

Building Type School	County Jackson	
Street 2323 Siskiyou Blvd		
City Medford	State OR	Zip 97504
Latitude 42.3203	Longitude 122.83903	
Tracking Code RVS in 2006	Inspection Date 7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	-0.5	0	0	-0.2	0	0	4.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
W1	4.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hoover Elementary School

Jack_sch24A

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Elevation View also shows an out of plane lateral system.		S Plan Irregularity Primary	

Hoover Elementary School

Medford SD 549C

Jack_sch24B

Building Type	County
School	Jackson
Street	
2323 Siskiyou Blvd	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.3203	122.8386
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary	W2	4.8	-3	0	0	0	-0.8	0	0	1
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Hoover Elementary School

Jack_sch24B

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: 2 to 3 Changes None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Plan Irregularity Primary Three walls are RM1 and one is wood.			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Medford SD 549C

Jack_sch24C

Building Type	County
School	Jackson
Street	
2323 Siskiyou Blvd	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.32049	122.83857
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary	W2	4.8	-3	0	0	0	-0.8	0	0	1
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Hoover Elementary School

Jack_sch24C

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: 2 to 3 Changes None	
Falling Hazards None None None		Poor Conditions None None None	
 N Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Medford SD 549C

Jack_sch24D

Building Type	County
School	Jackson
Street	
2323 Siskiyou Blvd	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.32068	122.83863
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary	W2	4.8	-3	0	0	0	-0.8	0	0	1
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Jack_sch24D

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: 2 to 3 Changes None	
Falling Hazards None None None		Poor Conditions None None None	
 N Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Medford SD 549C

Jack_sch24E

Building Type	County
School	Jackson
Street	
2323 Siskiyou Blvd	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.32087	122.83864
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary	W2	4.8	-3	0	0	0	-0.8	0	0	1
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Jack_sch24E

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: 2 to 3 Changes None	
Falling Hazards None None None		Poor Conditions None None None	
 N Plan Irregularity Primary			



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Medford SD 549C

Jack_sch24F

Building Type	County
School	Jackson
Street	
2323 Siskiyou Blvd	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.32106	122.83861
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hoover Elementary School

Jack_sch24F

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Torsion: Building Shape None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>NE Elevation View shows a RM wall on the left and a W2 wall on the right.</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Medford SD 549C

Jack_sch24G

Building Type School	County Jackson	
Street 2323 Siskiyou Blvd		
City Medford	State OR	Zip 97504
Latitude 42.32107	Longitude 122.83816	
Tracking Code RVS in 2006	Inspection Date 7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	0	-0.2	0	0	5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
W1	5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Jack_sch24G

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1970
Total Area (square ft) 51611	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Hoover Elementary School

Medford SD 549C

Jack_sch24H

Building Type School	County Jackson	
Street 2323 Siskiyou Blvd		
City Medford	State OR	Zip 97504
Latitude 42.3209	Longitude 122.83817	
Tracking Code RVS in 2006	Inspection Date 7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
W2	4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hoover Elementary School

Jack_sch24H

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1970
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 A photograph showing the NW elevation of Hoover Elementary School. The building is a single-story structure with light-colored horizontal siding. It features a small entrance area with a door and a window above it. A paved walkway leads to the entrance, and there are green bushes and trees in the foreground and background.			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Medford SD 549C

Jack_sch24I

Building Type	County	
School	Jackson	
Street		
2323 Siskiyou Blvd		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.32062	122.83812	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Hoover Elementary School

Jack_sch241

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1970
Total Area (square ft) 51611	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		None None None	
Falling Hazards		Poor Conditions	
None None None		None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Jack_sch24J

Medford SD 549C

Building Type School	County Jackson	
Street 2323 Siskiyou Blvd		
City Medford	State OR	Zip 97504
Latitude 42.3206	Longitude 122.83913	
Tracking Code RVS in 2006	Inspection Date 7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Hoover Elementary School

Jack_sch24J

Enrollment 484	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 51611	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
 NW Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries