

Oak Grove Elementary School

Medford SD 549C

Jack_sch30A

Building Type	County	
School	Jackson	
Street		
2838 Jacksonville Hwy		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.32419	122.90929	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	-1	0	-0.6	0	0	-1.1
Secondary	URM	3.4	-1.5	-0.5	-0.4	0	-0.4	0	0	0.6
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
C1	-1.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Oak Grove Elementary School

Jack_sch30A

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built Pre 1900
Total Area (square ft) 47329	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
None		Poor Masonry	
None		Poor Concrete	
None		None	
			
NE Plan Irregularity Primary	NE Secondary Structural Type	NW Plan Irregularity Secondary	
			
NE General Site	W Poor Condition		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oak Grove Elementary School

Medford SD 549C

Jack_sch30B

Building Type	County
School	Jackson
Street	
2838 Jacksonville Hwy	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.3241	122.90971
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	-0.4	0	-0.8	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Oak Grove Elementary School

Jack_sch30B

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1940
Total Area (square ft) 47329	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: L Shaped		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N Vertical Irregularity Primary .Plan Irregularity Secondary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oak Grove Elementary School

Medford SD 549C

Jack_sch30C

Building Type	County
School	Jackson
Street	
2838 Jacksonville Hwy	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.32439	122.90991
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	-0.4	0	-0.8	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Oak Grove Elementary School

Jack_sch30C

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1940
Total Area (square ft) 47329	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>E Vertical Irregularity Primary Plan Irregularity</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oak Grove Elementary School

Medford SD 549C

Jack_sch30D

Building Type	County
School	Jackson
Street	
2838 Jacksonville Hwy	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.32478	122.90995
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Oak Grove Elementary School

Jack_sch30D

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1990
Total Area (square ft) 47329	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Oak Grove Elementary School

Medford SD 549C

Jack_sch30E

Building Type	County	
School	Jackson	
Street		
2838 Jacksonville Hwy		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.32486	122.90953	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Oak Grove Elementary School

Jack_sch30E

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1990
Total Area (square ft) 47329	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Oak Grove Elementary School

Medford SD 549C

Jack_sch30F

Building Type	County
School	Jackson
Street	
2838 Jacksonville Hwy	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.32464	122.90966
Tracking Code	Inspection Date
RVS in 2006	7/21/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Oak Grove Elementary School

Jack_sch30F

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1960
Total Area (square ft) 47329	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Oak Grove Elementary School

Medford SD 549C

Jack_sch30G

Building Type	County	
School	Jackson	
Street		
2838 Jacksonville Hwy		
City	State	Zip
Medford	OR	97501
Latitude	Longitude	
42.32443	122.90943	
Tracking Code	Inspection Date	
RVS in 2006	7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
W2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Oak Grove Elementary School

Jack_sch30G

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1930
Total Area (square ft) 47329	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
 NW Plan Irregularity Primary		 N Falling Hazard	 NE Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Oak Grove Elementary School

Medford SD 549C

Jack_sch30H

Building Type School	County Jackson	
Street 2838 Jacksonville Hwy		
City Medford	State OR	Zip 97501
Latitude 42.32466	Longitude 122.90908	
Tracking Code RVS in 2006	Inspection Date 7/21/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oak Grove Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Oak Grove Elementary School

Jack_sch30H

Enrollment 455	Year Built (Field Verified) 1891	Year Built (Alt. Source) 1891	Est. Decade Built 1950
Total Area (square ft) 47329	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Plan Irregularity Primary			