

# Roosevelt Elementary School

Medford SD 549C

Jack\_sch32A

Building Type	County	
School	Jackson	
Street		
112 Lindley St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.32988	122.85741	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	0	-0.4	0	-0.4	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Roosevelt Elementary School

### Final RVS Score

Final Type	Final Score
URM	1.1

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Roosevelt Elementary School

Jack\_sch32A

Enrollment 385	Year Built (Field Verified) 1912	Year Built (Alt. Source) 1912	Est. Decade Built 1910
Total Area (square ft) 42433	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards Parapets: Unreinforced Around Entire Building Other: Heavy cornice or other overhead decoration None		Poor Conditions Poor Masonry Poor masonry joint condition None	
			
W Falling Hazard	W Poor Condition	NW Elevation View	
			
N Falling Hazard	NE Vertical Irregularity Primary	E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Roosevelt Elementary School

Medford SD 549C

Jack\_sch32B

Building Type	County	
School	Jackson	
Street		
112 Lindley St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.32978	122.85707	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	3.4	-1.5	-0.5	0	0	-0.6	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Roosevelt Elementary School

## Final RVS Score

Final Type	Final Score
RM2	0.8

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Roosevelt Elementary School

Jack\_sch32B

Enrollment 385	Year Built (Field Verified) 1912	Year Built (Alt. Source) 1912	Est. Decade Built 1980
Total Area (square ft) 42433	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Vertical Irregularity Primary To building "A". Also shows a reentrant corner.		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Roosevelt Elementary School

Medford SD 549C

Jack\_sch32C

Building Type	County	
School	Jackson	
Street		
112 Lindley St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.32998	122.85684	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Roosevelt Elementary School

## Final RVS Score

Final Type	Final Score
RM1	0.8

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Roosevelt Elementary School

Jack\_sch32C

Enrollment 385	Year Built (Field Verified) 1912	Year Built (Alt. Source) 1912	Est. Decade Built 1990
Total Area (square ft) 42433	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>S      Other Joint to "A"</p>			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Roosevelt Elementary School

Medford SD 549C

Jack\_sch32D

Building Type	County	
School	Jackson	
Street		
112 Lindley St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.32961	122.85754	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Roosevelt Elementary School

**Final RVS Score**

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)
-----------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Roosevelt Elementary School

Jack\_sch32D

Enrollment 385	Year Built (Field Verified) 1912	Year Built (Alt. Source) 1912	Est. Decade Built 1980
Total Area (square ft) 42433	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	