

Hedrick Middle School

Medford SD 549C

Jack_sch34A

Building Type	County	
School	Jackson	
Street		
1501 E Jackson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.33151	122.85301	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hedrick Middle School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Hedrick Middle School

Jack_sch34A

Enrollment 956	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1960
Total Area (square ft) 146065	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		Short Columns	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	General Site	E	Plan Irregularity Primary
			
NE	Plan Irregularity Secondary		
N	Other Joint to building D		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hedrick Middle School

Medford SD 549C

Jack_sch34B

Building Type	County	
School	Jackson	
Street		
1501 E Jackson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.33168	122.85409	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hedrick Middle School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hedrick Middle School

Jack_sch34B

Enrollment 956	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 146065	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
NW Falling Hazard		NW Elevation View elevation step and reentrant corner.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hedrick Middle School

Medford SD 549C

Jack_sch34C

Building Type	County	
School	Jackson	
Street		
1501 E Jackson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.332	122.85411	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	3.2	0	-0.5	0	0	-0.6	0	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hedrick Middle School

Final RVS Score

Final Type	Final Score
PC1	2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hedrick Middle School

Jack_sch34C

Enrollment 956	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1990	Est. Decade Built 1990
Total Area (square ft) 146065	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions Cracks None None	
 NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hedrick Middle School

Medford SD 549C

Jack_sch34D

Building Type	County	
School	Jackson	
Street		
1501 E. Jackson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.33188	122.8534	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hedrick Middle School

Final RVS Score

Final Type	Final Score
C2	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hedrick Middle School

Jack_sch34D

Enrollment 956	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1980
Total Area (square ft) 146065	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Vertical Irregularity Primary		N Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries