


South Medford High School

Medford SD 549C

Jack_sch35A

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.316	122.87176
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


South Medford High School

Final RVS Score

Final Type	Final Score
C2	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

South Medford High School

Jack_sch35A

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1980
Total Area (square ft) 259366	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Plan Irregularity Primary reentrant corner		S Plan Irregularity Primary reentrant corner	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35B

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31601	122.87301
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	0	-0.5	-1	0	-0.6	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Medford High School

Final RVS Score

Final Type	Final Score
C1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Jack_sch35B

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1930		
Total Area (square ft) 259366	Number of Stories 2	Basement	Pounding Potential No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes			
Reentrant Corners: Other (Adjacent Build/Entity)		None			
Out of Plane Lateral-Force-Resistance Elements		None			
Falling Hazards		Poor Conditions			
Unreinforced Chimneys		None			
Parapets: General		None			
None		None			
	S Falling Hazard		S Falling Hazard big parapet		S Plan Irregularity Primary
	S Basement				



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35C

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31644	122.87324
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	-2	-0.5	0	0	-0.6	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Medford High School

Final RVS Score

Final Type	Final Score
C1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Jack_sch35C

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1980
Total Area (square ft) 259366	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Internal Discontinuous Diaphram (large internal opening) Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards Parapets: General None None		Poor Conditions None None None	
 N Elevation View		 N Falling Hazard	
		 NE Vertical Irregularity Secondary Also plan irreg.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35D

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31639	122.87263
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	-0.8	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Medford High School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Jack_sch35D

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1940	Est. Decade Built
Total Area (square ft) 259366	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) Soft Story None	
Falling Hazards None None None		Poor Conditions None None None	
 W Vertical Irregularity Primary Very large opening inside.			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35E

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31546	122.87235
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


South Medford High School

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Jack_sch35E

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1960
Total Area (square ft) 259366	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	
			
N Elevation View		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35F

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31521	122.87234
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	-0.8	0	0	-0.1
Secondary	RM1	3.6	-2	-0.5	-0.4	0	-0.8	0	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0


South Medford High School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Jack_sch35F

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1930
Total Area (square ft) 259366	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Torsion: Eccentric Stiffness None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Secondary Structural Type		 SW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35G

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31658	122.87103
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	0	0	0	0	-0.6	0	0	2.4
Secondary	C2	3.6	0	0	0	0	-0.8	0	0	2.8
Tertiary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8

South Medford High School

Final RVS Score

Final Type	Final Score
C1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Jack_sch35G

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1960
Total Area (square ft) 259366	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Tertiary Structural Type		SE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Medford High School

Medford SD 549C

Jack_sch35H

Building Type	County
School	Jackson
Street	
815 S Oakdale Ave	
City	State Zip
Medford	OR 97501
Latitude	Longitude
42.31662	122.86989
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	3	0	0	0	0	-0.6	0	0	2.4
Secondary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Tertiary		0	0	0	0	0	0	0	0	0

South Medford High School

Final RVS Score

Final Type	Final Score
C1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

South Medford High School

Jack_sch35H

Enrollment 1887	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1960
Total Area (square ft) 259366	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries