

North Medford High School

Medford SD 549C

Jack_sch36A

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34718	122.85161
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36A

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Large Diaphragm or Central Opening None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Medford SD 549C

Jack_sch36B

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34648	122.85139
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	3.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36B

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Plan Irregularity Primary			

North Medford High School

Medford SD 549C

Jack_sch36C

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.3462	122.85039
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36C

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

North Medford High School

Medford SD 549C

Jack_sch36D

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34592	122.85022
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	3.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36D

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Plan Irregularity Primary		SE Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Medford SD 549C

Jack_sch36E

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34588	122.84955
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36E

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Medford SD 549C

Jack_sch36F

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34641	122.84984
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36F

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Plan Irregularity Primary			

North Medford High School

Medford SD 549C

Jack_sch36G

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34709	122.84989
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	-0.8	0	0	3.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	3.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36G

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped Reentrant Corners: U shaped None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Medford SD 549C

Jack_sch36H

Building Type	County	
School	Jackson	
Street		
1900 N Keene Way Dr		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34782	122.84981	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary	C1	3	-2	0	0	0	-0.6	0	0	0.4
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
C1	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36H

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Internal Discontinuous Diaphram (large internal opening) None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Secondary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Medford SD 549C

Jack_sch36I

Building Type	County	
School	Jackson	
Street		
1900 N Keene Way Dr		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34812	122.85057	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch361

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

North Medford High School

Medford SD 549C

Jack_sch36J

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.3479	122.85113
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36J

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Very Irregular Changes	
Non-Parallel System		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Elevation View		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36K

Medford SD 549C

Building Type	County	
School	Jackson	
Street		
1900 N Keene Way Dr		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34726	122.85082	
Tracking Code	Inspection Date	
RVS in 2006	7/11/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card


North Medford High School

Final RVS Score

Final Type	Final Score
W2	3.5

FEMA-154 Collapse Potential

Low (<1%)



North Medford High School

Jack_sch36K

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Medford SD 549C

Jack_sch36L

Building Type	County
School	Jackson
Street	
1900 N Keene Way Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34791	122.85162
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0


North Medford High School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Medford High School

Jack_sch36L

Enrollment 1941	Year Built (Field Verified) 1967	Year Built (Alt. Source) 1967	Est. Decade Built 1960
Total Area (square ft) 192822	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries