

Orchard Hill Elementary School

Phoenix-Talent SD 4

Jack_sch41A

Building Type	County
School	Jackson
Street	
1011 La Loma Dr	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.30853	122.83023
Tracking Code	Inspection Date
RVS in 2006	7/11/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Orchard Hill Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Orchard Hill Elementary School

Jack_sch41A

Enrollment 354	Year Built (Field Verified) 1983	Year Built (Alt. Source) 1983	Est. Decade Built 1980
Total Area (square ft) 50182	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Non-Parallel System		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Elevation View	S Elevation View non-parallel lateral system.	S Vertical Irregularity Primary	
			
W Vertical Irregularity Primary	E Elevation View	E Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries