

Wilson Elementary School

Medford SD 549C

Jack_sch43A

Building Type	County	
School	Jackson	
Street		
1400 Johnson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34552	122.86663	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Wilson Elementary School

Jack_sch43A

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Wilson Elementary School

Medford SD 549C

Jack_sch43B

Building Type	County
School	Jackson
Street	
1400 Johnson St	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34524	122.86665
Tracking Code	Inspection Date
RVS in 2006	7/6/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	3.4	0	-0.5	0	0	-0.6	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM2	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Wilson Elementary School

Jack_sch43B

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Plan Irregularity Primary		E Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
 Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Medford SD 549C

Jack_sch43C

Building Type	County
School	Jackson
Street	
1400 Johnson St	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34549	122.86604
Tracking Code	Inspection Date
RVS in 2006	7/6/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Wilson Elementary School

Jack_sch43C

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Medford SD 549C

Jack_sch43D

Building Type	County	
School	Jackson	
Street		
1400 Johnson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34537	122.86578	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Jack_sch43D

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Other Joint to "E"			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Medford SD 549C

Jack_sch43E

Building Type	County
School	Jackson
Street	
1400 Johnson St	
City	State Zip
Medford	OR 97504
Latitude	Longitude
42.34525	122.86604
Tracking Code	Inspection Date
RVS in 2006	7/6/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	-0.8	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Wilson Elementary School

Jack_sch43E

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Wilson Elementary School

Medford SD 549C

Jack_sch43F

Building Type	County	
School	Jackson	
Street		
1400 Johnson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34525	122.86724	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Jack_sch43F

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		None None None	
Falling Hazards		Poor Conditions	
None None None		None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Medford SD 549C

Jack_sch43G

Building Type	County	
School	Jackson	
Street		
1400 Johnson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34533	122.86772	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Wilson Elementary School

Jack_sch43G

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Wilson Elementary School

Medford SD 549C

Jack_sch43H

Building Type	County	
School	Jackson	
Street		
1400 Johnson St		
City	State	Zip
Medford	OR	97504
Latitude	Longitude	
42.34548	122.86727	
Tracking Code	Inspection Date	
RVS in 2006	7/6/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	-0.8	0	0	0.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wilson Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.8

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Wilson Elementary School

Jack_sch43H

Enrollment 572	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 44204	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries