

Little Butte School

Eagle Point SD 9

Jack_sch44A

Building Type	County
School	Jackson
Street	
12 N Shasta Ave	
City	State Zip
Eagle Point	OR 97524
Latitude	Longitude
42.47167	122.79936
Tracking Code	Inspection Date
RVS in 2006	7/17/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	-0.4	0	-0.8	0	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Little Butte School

Final RVS Score

Final Type	Final Score
C2	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Little Butte School

Jack_sch44A

Enrollment 462	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1920
Total Area (square ft) 44760	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Plan Irregularity Secondary	E	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Little Butte School

Eagle Point SD 9

Jack_sch44B

Building Type	County
School	Jackson
Street	
12 N Shasta Ave	
City	State Zip
Eagle Point	OR 97524
Latitude	Longitude
42.47143	122.79901
Tracking Code	Inspection Date
RVS in 2006	7/17/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Little Butte School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Little Butte School

Jack_sch44B

Enrollment 462	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 44760	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E General Site		N Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Little Butte School

Eagle Point SD 9

Jack_sch44C

Building Type	County
School	Jackson
Street	
12 N Shasta Ave	
City	State Zip
Eagle Point	OR 97524
Latitude	Longitude
42.47199	122.79859
Tracking Code	Inspection Date
RVS in 2006	7/17/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Secondary	C2	3.6	0	-0.5	0	0	-0.8	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Little Butte School

Final RVS Score

Final Type	Final Score
RM1	2.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Little Butte School

Jack_sch44C

Enrollment 462	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 44760	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Torsion: Eccentric Stiffness None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Vertical Irregularity Primary		NW Plan Irregularity Primary	
			
		W Secondary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries