

Shady Cove School

Eagle Point SD 9

Jack_sch45A

Building Type	County
School	Jackson
Street	
37 Schoolhouse Ln	
City	State Zip
Shady Cove	OR 97539
Latitude	Longitude
42.62254	122.80978
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	-0.4	0	0	0.6
Secondary	W2	4.8	-3	-0.5	-0.2	0	-0.8	0	0	0.3
Tertiary		0	0	0	0	0	0	0	0	0

Shady Cove School

Final RVS Score

Final Type	Final Score
W2	0.3

FEMA-154 Collapse Potential

High (>10%)



Shady Cove School

Jack_sch45A

Enrollment 273	Year Built (Field Verified) 1928	Year Built (Alt. Source) 1928	Est. Decade Built 1920
Total Area (square ft) 41071	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
SE General Site	E Vertical Irregularity Primary	N Vertical Irregularity Primary	
			
S Plan Irregularity Secondary	W Plan Irregularity Primary	S General Site	
			
S Falling Hazard			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Shady Cove School

Eagle Point SD 9

Jack_sch45B

Building Type	County
School	Jackson
Street	
37 Schoolhouse Ln	
City	State Zip
Shady Cove	OR 97539
Latitude	Longitude
42.62218	122.8099
Tracking Code	Inspection Date
RVS in 2006	7/18/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	-0.4	0	-0.8	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Shady Cove School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Shady Cove School

Jack_sch45B

Enrollment 273	Year Built (Field Verified) 1928	Year Built (Alt. Source) 1928	Est. Decade Built 1940
Total Area (square ft) 41071	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries