

Three Rivers VFD

Jeff_fir01A

Three Rivers VFD

Building Type		County	
Fire - RFPD		Jefferson	
Street			
5055 SW Lakeview Dr.			
City	State	Zip	
Culver	OR	97734	
Latitude		Longitude	
44.56815		121.3638	
Tracking Code		Inspection Date	
RVS in 2006		7/29/2006	

Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	-0.5	0	1.6	-0.2	0	0	6.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Three Rivers VFD

Final RVS Score

Final Type

Final Score

W1

6.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1990	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1500	1	No	No

Plan Irregularities	Vertical Irregularities
Torsion: Eccentric Stiffness	None
Reentrant Corners: L Shaped	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None

