

South Middle School

Grants Pass SD 7

Jose_sch05A

| | |
|------------------|-----------------|
| Building Type | County |
| School | Josephine |
| Street | |
| 350 W Harbeck Rd | |
| City | State Zip |
| Grants Pass | OR 97527 |
| Latitude | Longitude |
| 42.41589 | 123.33399 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 7/19/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 2.8 | -1 | -0.5 | 0 | 0 | -0.4 | 0 | 0 | 0.9 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

South Middle School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 0.9 |

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

South Middle School

Jose_sch05A

| | | | |
|--|-------------------------------------|--|-------------------------------|
| Enrollment 666 | Year Built (Field Verified) 1958 | Year Built (Alt. Source) 1958 | Est. Decade Built 1940 |
| Total Area (square ft) 74921 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: 2 to 3 Changes | |
| Out of Plane Lateral-Force-Resistance Elements | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| SE | Plan Irregularity Primary | S | Vertical Irregularity Primary |
| | |  | |
| | | W | Plan Irregularity Secondary |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries