

Merle West Medical Center - Klamath Falls

NFP - Merle West

Klam_hos01A

Building Type	County	
Hospital	Klamath	
Street		
2865 Daggett Ave		
City	State	Zip
Klamath Falls	OR	97601
Latitude	Longitude	
42.25316	121.78483	
Tracking Code	Inspection Date	
New Building	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.9	-1.5	-0.5	0	0	0	0	0	0.9
Secondary	C1	2.9	-1.5	-0.5	0	0	0	0	0	0.9
Tertiary	RM1	3.2	-1	-0.5	0	0	0	0	0	1.7

Merle West Medical Center -
Klamath Falls

Final RVS Score

Final Type	Final Score
C1	0.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Merle West Medical Center - Klamath Falls

Klam_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	4	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Plan Irregularity Primary		NE Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Merle West Medical Center - Klamath Falls

NFP - Merle West

Klam_hos01B

Building Type	County	
Hospital	Klamath	
Street		
2865 Daggett Ave		
City	State	Zip
Klamath Falls	OR	97601
Latitude	Longitude	
42.25306	121.7841	
Tracking Code	Inspection Date	
New Building	7/20/2006	



Merle West Medical Center -
Klamath Falls

Final RVS Score


Final Type Final Score

C2 1.3

FEMA-154 Collapse Potential

Low (<1%)

FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Merle West Medical Center - Klamath Falls

Klam_hos01B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	

Merle West Medical Center - Klamath Falls

NFP - Merle West

Klam_hos01C

Building Type	County	
Hospital	Klamath	
Street		
2865 Daggett Ave		
City	State	Zip
Klamath Falls	OR	97601
Latitude	Longitude	
42.25256	121.78542	
Tracking Code	Inspection Date	
New Building	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	S2	3	-1.5	-0.5	0	0	0	0	0	1
Tertiary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3

Merle West Medical Center -
Klamath Falls

Final RVS Score

Final Type	Final Score
S2	1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Merle West Medical Center - Klamath Falls

Klam_hos01C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
S	Falling Hazard	SE	Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Merle West Medical Center - Klamath Falls

NFP - Merle West

Klam_hos01D

Building Type	County	
Hospital	Klamath	
Street		
2865 Daggett Ave		
City	State	Zip
Klamath Falls	OR	97601
Latitude	Longitude	
42.25259	121.78477	
Tracking Code	Inspection Date	
New Building	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3	-1.5	-0.5	0	0	0	0	0	1
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3

Merle West Medical Center -
Klamath Falls

Final RVS Score

Final Type	Final Score
S2	1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Merle West Medical Center - Klamath Falls

Klam_hos01D

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Vertical Irregularity Primary		E Plan Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries