

Roosevelt Elementary School

Klamath Falls City Schools

Klam_sch02A

Building Type	County	
School	Klamath	
Street		
1125 Eldorado St		
City	State	Zip
Klamath Falls	OR	97601
Latitude	Longitude	
42.23842	121.77485	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	-0.2	0	-0.4	0	0	-0.3
Secondary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary	RM1	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1

Roosevelt Elementary School

Final RVS Score

Final Type	Final Score
URM	-0.3

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Roosevelt Elementary School

Klam_sch02A

Enrollment 345	Year Built (Field Verified) 1929	Year Built (Alt. Source) 1929	Est. Decade Built 1920
Total Area (square ft) 25360	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped Reentrant Corners: E Shaped None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) Building On Hill or Sloped Site None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
W General Site		E Falling Hazard	

Roosevelt Elementary School

Klamath Falls City Schools

Klam_sch02B

Building Type	County
School	Klamath
Street	
1125 Eldorado St	
City	State Zip
Klamath Falls	OR 97601
Latitude	Longitude
42.23857	121.77472
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	-0.2	0	-0.4	0	0	-0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Roosevelt Elementary School

Final RVS Score

Final Type	Final Score
URM	-0.3

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Roosevelt Elementary School

Klam_sch02B

Enrollment 345	Year Built (Field Verified) 1929	Year Built (Alt. Source) 1929	Est. Decade Built 1930
Total Area (square ft) 25360	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Primary Structural Type		 SE General Site	
 E Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Roosevelt Elementary School

Klamath Falls City Schools

Klam_sch02C

Building Type	County	
School	Klamath	
Street		
1125 Eldorado St		
City	State	Zip
Klamath Falls	OR	97601
Latitude	Longitude	
42.23848	121.77462	
Tracking Code	Inspection Date	
RVS in 2006	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	RM1	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary	C3	1.6	-1	-0.5	-0.2	0	-0.4	0	0	-0.5

Roosevelt Elementary School

Final RVS Score

Final Type	Final Score
C3	-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Roosevelt Elementary School

Klam_sch02C

Enrollment 345	Year Built (Field Verified) 1929	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 25360	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Other addition			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries