

Ponderosa Junior High School

Klamath Falls City Schools

Klam_sch19A

Building Type	County
School	Klamath
Street	
2554 Main St	
City	State Zip
Klamath Falls	OR 97601
Latitude	Longitude
42.22816	121.76048
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Ponderosa Junior High School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Ponderosa Junior High School

Klam_sch19A

Enrollment 478	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 84435	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
 SE Falling Hazard			

Ponderosa Junior High School

Klamath Falls City Schools

Klam_sch19B

Building Type	County
School	Klamath
Street	
2554 Main St	
City	State Zip
Klamath Falls	OR 97601
Latitude	Longitude
42.22799	121.76128
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4

Ponderosa Junior High School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ponderosa Junior High School

Klam_sch19B

Enrollment 478	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1960
Total Area (square ft) 84435	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary		S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ponderosa Junior High School

Klamath Falls City Schools

Klam_sch19C

Building Type	County
School	Klamath
Street	
2554 Main St	
City	State Zip
Klamath Falls	OR 97601
Latitude	Longitude
42.22758	121.76109
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Ponderosa Junior High School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ponderosa Junior High School

Klam_sch19C

Enrollment 478	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1970
Total Area (square ft) 84435	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Plan Irregularity Primary			

Ponderosa Junior High School

Klamath Falls City Schools

Klam_sch19D

Building Type	County
School	Klamath
Street	
2554 Main St	
City	State Zip
Klamath Falls	OR 97601
Latitude	Longitude
42.22724	121.76166
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W2	3.8	-2	-0.5	0	2.4	-0.4	0	0	3.3
Tertiary	C2	2.8	-1	-0.5	0	2.4	-0.4	0	0	3.3

Ponderosa Junior High School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ponderosa Junior High School

Klam_sch19D

Enrollment 478	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1990
Total Area (square ft) 84435	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other Reentrant Corners: Other None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Steps in Elevation View: Single Change None	
Falling Hazards None None None		Poor Conditions None None None	
 W Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries