

Joseph Conger Elementary School

Klamath Falls City Schools

Klam_sch23A

Building Type		County	
School		Klamath	
Street			
1700 California			
City	State	Zip	
Klamath Falls	OR	97601	
Latitude		Longitude	
42.23501		121.79583	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	-0.2	0	0	-0.6	0	-0.5
Secondary	C2	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Tertiary		0	0	0	0	0	0	0	0	0

Joseph Conger Elementary School

Final RVS Score

Final Type

Final Score

URM

-0.5

FEMA-154 Collapse Potential

Very High (100%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
288		1930	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38849	1	Yes	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
None	None
None	None



S Other



E General Site



Joseph Conger Elementary School

Klamath Falls City Schools

Klam_sch23B

Building Type		County	
School		Klamath	
Street			
1700 California			
City	State	Zip	
Klamath Falls	OR	97601	
Latitude		Longitude	
42.23488		121.79603	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Secondary	RM1	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Tertiary		0	0	0	0	0	0	0	0	0

Joseph Conger Elementary School

Final RVS Score

Final Type

Final Score

C2

-0.3

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Joseph Conger Elementary School

Klam_sch23B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
288		1930	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38849	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



N General Site



OregonGeology

Joseph Conger Elementary School

Klamath Falls City Schools

Klam_sch23C

Building Type		County	
School		Klamath	
Street			
1700 California			
City	State	Zip	
Klamath Falls	OR	97601	
Latitude		Longitude	
42.23505		121.79635	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4

Joseph Conger Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
288		1930	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38849	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Plan Irregularity Primary



Joseph Conger Elementary School

Klamath Falls City Schools

Klam_sch23D

Building Type		County	
School		Klamath	
Street			
1700 California			
City	State	Zip	
Klamath Falls	OR	97601	
Latitude		Longitude	
42.23476		121.79595	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Joseph Conger Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
288		1930	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38849	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners:Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Joseph Conger Elementary School

Klamath Falls City Schools

Klam_sch23E

Building Type		County	
School		Klamath	
Street			
1700 California			
City	State	Zip	
Klamath Falls	OR	97601	
Latitude		Longitude	
42.23472		121.79627	
Tracking Code		Inspection Date	
RVS in 2006		7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

Joseph Conger Elementary School

Final RVS Score

Final Type

Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Joseph Conger Elementary School

Klam_sch23E

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
288		1930	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
38849	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Elevation View