

Lake District Hospital - Lakeview

NFP (LC Health District)

Lake_hos01A

Building Type Hospital	County Lake	
Street 700 S J St		
City Lakeview	State OR	Zip 97630
Latitude 42.18137	Longitude 120.3526	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	0	-1.2	0	3.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Lake District Hospital - Lakeview

Final RVS Score

Final Type	Final Score
W2	3.1

FEMA-154 Collapse Potential

Low (<1%)



Lake District Hospital - Lakeview

Lake_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1970	1971	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
Large Diaphragm or Central Opening		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
S Primary Structural Type looks like wood beams inside	S Primary Structural Type wood beams coming from inside going outside.	E Primary Structural Type wood beams	
			
S General Site	S Other smokestack	S General Site	
			
W General Site	N Primary Structural Type wood post and beams	N General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lake District Hospital - Lakeview

Lake_hos01A



W General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries