

# Paisley School

Paisley SD 11

Lake\_sch01A

|               |                 |       |
|---------------|-----------------|-------|
| Building Type | County          |       |
| School        | Lake            |       |
| Street        |                 |       |
| 260 Green St  |                 |       |
| City          | State           | Zip   |
| Paisley       | OR              | 97636 |
| Latitude      | Longitude       |       |
| 42.69332      | 120.54272       |       |
| Tracking Code | Inspection Date |       |
| RVS in 2006   | 7/7/2006        |       |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | C2   | 2.8         | -1         | 0          | -1       | 0          | 0      | 0      | -0.8   | 0         |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Paisley School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2         | 0           |

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Paisley School

Lake\_sch01A

|  |                                     |  |                           |
|--|-------------------------------------|--|---------------------------|
| Enrollment<br>85   | Year Built (Field Verified)<br>1917 | Year Built (Alt. Source)<br>1917   | Est. Decade Built<br>1910 |
| Total Area (square ft)<br>31869  | Number of Stories<br>2              | Basement   | Pounding Potential<br>No  |
| Plan Irregularities<br>None<br>None<br>None  |                                     | Vertical Irregularities<br>Steps in Elevation View: Single Change<br>Internal Discontinuous Diaphragm (large internal opening)<br>None |                           |
| Falling Hazards<br>None<br>None<br>None  |                                     | Poor Conditions<br>None<br>None<br>None  |                           |
|  |                                     |   |                           |
| N  | Field Verified Year Built           | W  | Primary Structural Type   |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Paisley School

Paisley SD 11

Lake\_sch01B

|               |                 |
|---------------|-----------------|
| Building Type | County          |
| School        | Lake            |
| Street        |                 |
| 260 Green St  |                 |
| City          | State Zip       |
| Paisley       | OR 97636        |
| Latitude      | Longitude       |
| 42.69329      | 120.5422        |
| Tracking Code | Inspection Date |
| RVS in 2006   | 7/7/2006        |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W2   | 3.8         | -2         | -0.5       | 0        | 0          | 0      | 0      | -0.8   | 0.5       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Paisley School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2         | 0.5         |

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Paisley School

Lake\_sch01B

|   |                                     |  |                           |
|---|-------------------------------------|--|---------------------------|
| Enrollment<br>85  | Year Built (Field Verified)<br>1917 | Year Built (Alt. Source)<br>1917   | Est. Decade Built<br>1960 |
| Total Area (square ft)<br>31869   | Number of Stories<br>1              | Basement   | Pounding Potential<br>No  |
| Plan Irregularities<br>Reentrant Corners: Other<br>None<br>None                                       |                                     | Vertical Irregularities<br>Steps in Elevation View: Single Change (Adjacent Building/Entity)<br>None<br>None |                           |
| Falling Hazards<br>None<br>None<br>None   |                                     | Poor Conditions<br>None<br>None<br>None  |                           |
| <br>S General Site  |                                     | <br>S General Site        |                           |
|   |                                     | <br>W Elevation View     |                           |
| <br>S General Site |                                     |  |                           |



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Paisley School

Paisley SD 11

Lake\_sch01C

|                              |                             |              |
|------------------------------|-----------------------------|--------------|
| Building Type<br>School      | County<br>Lake              |              |
| Street<br>260 Green St       |                             |              |
| City<br>Paisley              | State<br>OR                 | Zip<br>97636 |
| Latitude<br>42.69347         | Longitude<br>120.54219      |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>7/7/2006 |              |



Seismicity Zone: High

**FEMA 154 Rapid Visual Screening Score Card**

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | -1         | -0.5       | 0        | 0          | 0      | 0      | -0.4   | 0.9       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

**Paisley School**

**Final RVS Score**

|                   |                    |
|-------------------|--------------------|
| Final Type<br>RM1 | Final Score<br>0.9 |
|-------------------|--------------------|

**FEMA-154 Collapse Potential**

|             |
|-------------|
| High (>10%) |
|-------------|



# Paisley School

Lake\_sch01C

|   |                                     |  |                           |
|---|-------------------------------------|--|---------------------------|
| Enrollment<br>85  | Year Built (Field Verified)<br>1917 | Year Built (Alt. Source)<br>1917   | Est. Decade Built<br>1980 |
| Total Area (square ft)<br>31869   | Number of Stories<br>1              | Basement   | Pounding Potential<br>No  |
| Plan Irregularities<br>Reentrant Corners:Other (Adjacent Build/Entity)<br>None<br>None                          |                                     | Vertical Irregularities<br>Steps in Elevation View: Single Change (Adjacent Building/Entity)<br>None<br>None |                           |
| Falling Hazards<br>None<br>None<br>None   |                                     | Poor Conditions<br>None<br>None<br>None  |                           |
| <br>S Primary Structural Type |                                     | <br>W Elevation View      |                           |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Paisley School

Paisley SD 11

Lake\_sch01D

|               |                 |
|---------------|-----------------|
| Building Type | County          |
| School        | Lake            |
| Street        |                 |
| 260 Green St  |                 |
| City          | State Zip       |
| Paisley       | OR 97636        |
| Latitude      | Longitude       |
| 42.6937       | 120.54269       |
| Tracking Code | Inspection Date |
| RVS in 2006   | 7/7/2006        |

Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | C2   | 2.8         | 0          | 0          | 0        | 0          | 0      | 0      | -0.8   | 2         |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Paisley School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2         | 2           |

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Paisley School

Lake\_sch01D

|   |                                     |   |                           |
|---|-------------------------------------|---|---------------------------|
| Enrollment<br>85                            | Year Built (Field Verified)<br>1969 | Year Built (Alt. Source)<br>1917                | Est. Decade Built<br>1960 |
| Total Area (square ft)<br>31869             | Number of Stories<br>1              | Basement  | Pounding Potential<br>No  |
| Plan Irregularities<br>None<br>None<br>None |                                     | Vertical Irregularities<br>None<br>None<br>None |                           |
| Falling Hazards<br>None<br>None<br>None     |                                     | Poor Conditions<br>None<br>None<br>None         |                           |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Paisley School

Paisley SD 11

Lake\_sch01E

|               |                 |
|---------------|-----------------|
| Building Type | County          |
| School        | Lake            |
| Street        |                 |
| 260 Green St  |                 |
| City          | State Zip       |
| Paisley       | OR 97636        |
| Latitude      | Longitude       |
| 42.69302      | 120.54271       |
| Tracking Code | Inspection Date |
| RVS in 2006   | 7/7/2006        |

Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W1   | 4.4         | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 4.4       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Paisley School

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1         | 4.4         |

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Paisley School

Lake\_sch01E

|   |                                     |   |                           |
|---|-------------------------------------|---|---------------------------|
| Enrollment<br>85                            | Year Built (Field Verified)<br>1979 | Year Built (Alt. Source)<br>1917                | Est. Decade Built<br>1970 |
| Total Area (square ft)<br>31869             | Number of Stories<br>1              | Basement  | Pounding Potential<br>No  |
| Plan Irregularities<br>None<br>None<br>None |                                     | Vertical Irregularities<br>None<br>None<br>None |                           |
| Falling Hazards<br>None<br>None<br>None     |                                     | Poor Conditions<br>None<br>None<br>None         |                           |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries