

Fremont/Hay Elementary School

Lake County SD 7

Lake_sch02A

Building Type School	County Lake	
Street 500 S L St		
City Lakeview	State OR	Zip 97630
Latitude 42.18368	Longitude 120.3508	
Tracking Code RVS in 2006	Inspection Date 6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fremont/Hay Elementary School

Final RVS Score

Final Type	Final Score
W2	0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Fremont/Hay Elementary School

Lake_sch02A

Enrollment 324	Year Built (Field Verified) 1920	Year Built (Alt. Source) 1920	Est. Decade Built 1950
Total Area (square ft) 17500	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: H Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
W Elevation View		N Elevation View	
			
E General Site		N Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Fremont/Hay Elementary School

Lake County SD 7

Lake_sch02B

Building Type School	County Lake	
Street 600 S 5th St		
City Lakeview	State OR	Zip 97630
Latitude 42.18328	Longitude 120.34927	
Tracking Code RVS in 2006	Inspection Date 6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fremont/Hay Elementary School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Fremont/Hay Elementary School

Lake_sch02B

Enrollment 324	Year Built (Field Verified) 1920	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 17500	Number of Stories 1	Basement No	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	

Fremont/Hay Elementary School

Lake County SD 7

Lake_sch02C

Building Type	County	
School	Lake	
Street		
600 S 5th St		
City	State	Zip
Lakeview	OR	97630
Latitude	Longitude	
42.18313	120.34904	
Tracking Code	Inspection Date	
RVS in 2006	6/28/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	-0.2	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Fremont/Hay Elementary School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Fremont/Hay Elementary School

Lake_sch02C

Enrollment 324	Year Built (Field Verified) 1920	Year Built (Alt. Source) 1920	Est. Decade Built 1920
Total Area (square ft) 17500	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 E General Site		 W Elevation View	