

Daly Middle School

Lake County SD 7

Lake_sch04A

Building Type	County	
School	Lake	
Street		
220 S H St		
City	State	Zip
Lakeview	OR	97630
Latitude	Longitude	
42.18685	120.34891	
Tracking Code	Inspection Date	
RVS in 2006	6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	0	-1.6	-0.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Daly Middle School

Final RVS Score

Final Type	Final Score
URM	-0.6

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Daly Middle School

Lake_sch04A

Enrollment 119	Year Built (Field Verified) 1910	Year Built (Alt. Source) 1910	Est. Decade Built 1910
Total Area (square ft) 47814	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: L Shaped (Adjacent Build/Entity) None		None	
Falling Hazards		Poor Conditions	
Parapets: Unreinforced Around Entire Building		None	
None		None	
None		None	
 SE General Site		 E Primary Structural Type	
		 W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Daly Middle School

Lake County SD 7

Lake_sch04B

Building Type School	County Lake	
Street 220 S H St		
City Lakeview	State OR	Zip 97630
Latitude 42.18644	Longitude 120.34895	
Tracking Code RVS in 2006	Inspection Date 6/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	0	-1.6	-0.5
Secondary	W2	4.8	-3	-0.5	0	0	0	0	-1.8	-0.5
Tertiary		0	0	0	0	0	0	0	0	0

Daly Middle School

Final RVS Score

Final Type	Final Score
C2	-0.5

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Daly Middle School

Lake_sch04B

Enrollment 119	Year Built (Field Verified) 1910	Year Built (Alt. Source) 1910	Est. Decade Built 1970
Total Area (square ft) 47814	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
S Elevation View		W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries