

Branch - Florence Center

Lane CC

Lane_coc20A

Building Type Community_College	County Lane	
Street 3149 Oak St		
City Florence	State OR	Zip 97439
Latitude 43.99414	Longitude 124.10483	
Tracking Code RVS in 2006	Inspection Date 8/4/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Branch - Florence Center

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Branch - Florence Center

Lane_coc20A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1976	1976	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
15827	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW Primary Structural Type W2		NW General Site	
		NW Plan Irregularity Primary Reentrant Corner and vertical irregularity.	
			
W Plan Irregularity Primary Reentrant corner and a vertical irregularity.		E General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries