

Siuslaw Valley F & R

Lane_fir14A

Siuslaw Valley F & R

Building Type Fire - RFPD	County Lane	
Street 88973 Sutton Lake Rd		
City Florence	State OR	Zip 97439
Latitude 44.05155	Longitude 124.09594	
Tracking Code RVS in 2006	Inspection Date 8/3/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Siuslaw Valley F & R

Final RVS Score

Final Type	Final Score
S3	2.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Siuslaw Valley F & R

Lane_fir14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Primary Structural Type	SW	Plan Irregularity Primary Shows that the back wall is solid indicating a potential torsion problem.



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries