

Lane Rural Fire Rescue - Station 54 Alderwood

Lane_fir16A

Lane Rural Fire Rescue

| | | |
|---------------|-----------------|-------|
| Building Type | County | |
| Fire - RFPD | Lane | |
| Street | | |
| 22900 Hwy 36 | | |
| City | State | Zip |
| Eugene | OR | 97402 |
| Latitude | Longitude | |
| 44.16908 | 123.44177 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 8/3/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.2 | 0 | -0.5 | 0 | 0 | -0.4 | 0 | 0 | 2.3 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |


Lane Rural Fire Rescue - Station 54
Alderwood

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| S3 | 2.3 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Lane Rural Fire Rescue - Station 54 Alderwood

Lane_fir16A

| | | | |
|--|-----------------------------|--|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1980 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| Reentrant Corners: Other | | Steps in Elevation View: Single Change | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | | | |
| <p>SE Plan Irregularity Primary also shows vertical irregularity.</p> | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries