

# Swisshome-Deadwood RFPD

Lane\_fir41A

Swisshome - Deadwood RFPD

Building Type	County	
Fire - RFPD	Lane	
Street		
13283 Hwy 36		
City	State	Zip
Swisshome	OR	97480
Latitude	Longitude	
44.05765	123.80075	
Tracking Code	Inspection Date	
RVS in 2006	8/3/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Swisshome-Deadwood RFPD

## Final RVS Score

Final Type	Final Score
RM1	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Vertical Change in Structural Type (Soft over Stiff)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S	Primary Structural Type	W	Primary Structural Type and secondary structural type.
			
		NE	General Site



# Swisshome-Deadwood RFPD

Lane\_fir41B

Swisshome - Deadwood RFPD

Building Type	County	
Fire - RFPD	Lane	
Street		
13283 Hwy 36		
City	State	Zip
Swisshome	OR	97480
Latitude	Longitude	
44.05777	123.80085	
Tracking Code	Inspection Date	
RVS in 2006	8/3/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Swisshome-Deadwood RFPD

## Final RVS Score

Final Type	Final Score
S3	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Swisshome-Deadwood RFPD

Lane\_fir41B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Plan Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries