


Sacred Heart Medical Center - Eugene

PeaceHealth System NFP

Lane_hos03A

Building Type Hospital	County Lane	
Street 1255 Hilyard St		
City Eugene	State OR	Zip 97401
Latitude 44.04699	Longitude 123.08114	
Tracking Code New Building	Inspection Date 7/20/2006	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.2	-1	-0.5	-1	0	0	0	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sacred Heart Medical Center - Eugene

Final RVS Score

Final Type C2	Final Score 0.7
------------------	--------------------

FEMA-154 Collapse Potential

Low (<1%)



Lane_hos03



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

Lane_hos03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2008	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1840000	6	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
NE Plan Irregularity Primary and more vertical irr.		E Falling Hazard reinforced chimney?	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

PeaceHealth System NFP

Lane_hos03B

Building Type	County
Hospital	Lane
Street	
1255 Hilyard St	
City	State Zip
Eugene	OR 97401
Latitude	Longitude
44.04699	123.08069
Tracking Code	Inspection Date
New Building	7/20/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.2	0	-0.5	0	0	0	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sacred Heart Medical Center - Eugene

Final RVS Score

Final Type	Final Score
C2	2.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

Lane_hos03B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2008	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1840000	6	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

PeaceHealth System NFP

Lane_hos03C

Building Type	County	
Hospital	Lane	
Street		
1255 Hilyard St		
City	State	Zip
Eugene	OR	97401
Latitude	Longitude	
44.04648	123.0808	
Tracking Code	Inspection Date	
New Building	7/20/2006	



Sacred Heart Medical Center -
Eugene

Final RVS Score

Final Type Final Score

C1 0.9

FEMA-154 Collapse Potential

Low (<1%)

FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.9	-1.5	-0.5	0	0	0	0	0	0.9
Secondary	C2	3.2	-1	-0.5	0	0	0	0	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

Lane_hos03C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2008	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1840000	5	Yes	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
	NE	Plan Irregularity Primary	
S Pounding Potential pounding potential -- joint that is potentially not large enough for seismic isolation.			SE Vertical Irregularity Primary

Sacred Heart Medical Center - Eugene

PeaceHealth System NFP

Lane_hos03D

Building Type	County	
Hospital	Lane	
Street		
1255 Hilyard St		
City	State	Zip
Eugene	OR	97401
Latitude	Longitude	
44.04663	123.08156	
Tracking Code	Inspection Date	
New Building	7/20/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S4	3.2	-1	-0.5	0	0	0	0	0	1.7
Secondary	C1	2.9	-1.5	-0.5	0	0	0	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Sacred Heart Medical Center - Eugene

Final RVS Score

Final Type	Final Score
C1	0.9

FEMA-154 Collapse Potential

Low (<1%)



Sacred Heart Medical Center - Eugene

Lane_hos03D

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2008	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1840000	6	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		Steps in Elevation View: Single Change	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Vertical Irregularity Primary cantilever portions		W Vertical Irregularity Primary cantilever portions	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

PeaceHealth System NFP

Lane_hos03E

Building Type Hospital	County Lane	
Street 1255 Hilyard St		
City Eugene	State OR	Zip 97401
Latitude 44.04598	Longitude 123.08166	
Tracking Code New Building	Inspection Date 7/20/2006	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.9	-1.5	-0.5	0	0	0	0	0	0.9
Secondary	C2	3.2	-1	-0.5	0	2.4	0	0	0	4.1
Tertiary	S4	3.2	-1	-0.5	0	1.6	0	0	0	3.3

Sacred Heart Medical Center - Eugene

Final RVS Score

Final Type C1	Final Score 0.9
------------------	--------------------

FEMA-154 Collapse Potential

Low (<1%)







OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Sacred Heart Medical Center - Eugene

Lane_hos03E

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2008	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
1840000	6	Yes	No
Plan Irregularities		Vertical Irregularities	
Non-Parallel System		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
SE Vertical Irregularity Primary		SW Plan Irregularity Primary non-parallel	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries