

Edison Elementary School

Eugene SD 4J

Lane_sch06A

Building Type School	County Lane	
Street 1328 E 22nd Ave		
City Eugene	State OR	Zip 97403
Latitude 44.0353	Longitude 123.07237	
Tracking Code RVS in 2006	Inspection Date 1/29/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	0	0	0.3
Secondary	URM	1.8	-1	-0.5	-0.2	0	0	0	0	0.1
Tertiary	W2	3.8	-2	-0.5	-1	0	0	0	0	0.3

Edison Elementary School

Final RVS Score

Final Type	Final Score
URM	0.1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Edison Elementary School

Lane_sch06A

Enrollment 287	Year Built (Field Verified) 1926	Year Built (Alt. Source) 1926	Est. Decade Built 1920
Total Area (square ft) 42195	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Building On Hill or Sloped Site None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
NW Plan Irregularity Primary		W Secondary Structural Type	
			
SW Vertical Irregularity Primary		S Primary Structural Type	
			
W Primary Structural Type		S Elevation View wood infill area between brick wings	
			
S Tertiary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Edison Elementary School

Lane_sch06A



S Primary Structural Type



SE Elevation View



NE Vertical Irregularity Secondary



N Falling Hazard



N Field Verified Year Built



S Primary Structural Type