

Ellis Parker Elementary School

Eugene SD 4J

Lane_sch07A

Building Type		County	
School		Lane	
Street			
3875 Kincaid St			
City	State	Zip	
Eugene	OR	97405	
Latitude		Longitude	
44.01346		123.07509	
Tracking Code		Inspection Date	
RVS in 2006		1/29/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Ellis Parker Elementary School

Final RVS Score

Final Type

Final Score

RM1

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


Ellis Parker Elementary School

Lane_sch07A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
248	1952	1959	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40837	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Soft Story
None	Building On Hill or Sloped Site

Falling Hazards	Poor Conditions
Unreinforced Chimneys	None
Other: Ornamental Hazard Over Exit	None
None	None



E Seismic Upgrade



E Primary Structural Type



SE Elevation View



SW Falling Hazard



S Vertical Irregularity Tertiary



W Vertical Irregularity Secondary



SW Secondary Structural Type



N Vertical Irregularity Tertiary



NE Elevation View

Ellis Parker Elementary School

Lane_sch07B

Eugene SD 4J

Building Type		County	
School		Lane	
Street			
3875 Kincaid St			
City	State	Zip	
Eugene	OR	97405	
Latitude		Longitude	
44.01379		123.07497	
Tracking Code		Inspection Date	
RVS in 2006		1/29/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ellis Parker Elementary School

Final RVS Score

Final Type

Final Score

W2

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
248		1959	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
40837	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Reentrant Corners: Other (Adjacent Build/Entity)	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



W Plan Irregularity Secondary



E Elevation View



SE Plan Irregularity Primary

