

South Eugene High School

Eugene SD 4J

Lane_sch26A

Building Type	County
School	Lane
Street	
400 E 19th Ave	
City	State Zip
Eugene	OR 97401
Latitude	Longitude
44.03799	123.08669
Tracking Code	Inspection Date
SER & RVS2006	7/27/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	C1	2.5	-1.5	-0.5	0	0	0	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

South Eugene High School

Final RVS Score

Final Type	Final Score
C1	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Eugene High School

Lane_sch26A

Enrollment 1698	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1950
Total Area (square ft) 309614	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
Falling Hazards		Poor Conditions	
Other: General		Poor Concrete	
None		None	
None		None	
			
N General Site	N General Site	N General Site	
			
N Falling Hazard	S Poor Condition	SW Vertical Irregularity Primary also shows reentrant corner	
			
W Primary Structural Type	E Secondary Structural Type	E General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Eugene High School

Eugene SD 4J

Lane_sch26B

Building Type	County
School	Lane
Street	
400 E 19th Ave	
City	State Zip
Eugene	OR 97401
Latitude	Longitude
44.03743	123.08611
Tracking Code	Inspection Date
SER & RVS2006	7/27/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Eugene High School

Final RVS Score

Final Type	Final Score
S3	2.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

South Eugene High School

Lane_sch26B

Enrollment 1698	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1990
Total Area (square ft) 309614	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Plan Irregularity Primary		E Plan Irregularity Primary	

South Eugene High School

Eugene SD 4J

Lane_sch26C

Building Type	County	
School	Lane	
Street		
400 E 19th Ave		
City	State	Zip
Eugene	OR	97401
Latitude	Longitude	
44.03732	123.08413	
Tracking Code	Inspection Date	
SER & RVS2006	7/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	0	0	0	0	0	0	1.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Eugene High School

Final RVS Score

Final Type	Final Score
RM1	1.8

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Eugene High School

Lane_sch26C

Enrollment 1698	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1990
Total Area (square ft) 309614	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Vertical Irregularity Primary			