

# Elmira Elementary School

Fern Ridge SD 28J

Lane\_sch44A

Building Type School	County Lane	
Street 88960 Territorial Hwy		
City Elmira	State OR	Zip 97437
Latitude 44.07245	Longitude 123.35412	
Tracking Code RVS in 2006	Inspection Date 7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Elmira Elementary School

### Final RVS Score

Final Type	Final Score
RM1	2.2

### FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Elmira Elementary School

Lane\_sch44A

Enrollment 287	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1980
Total Area (square ft) 36486	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Elmira Elementary School

Fern Ridge SD 28J

Lane\_sch44B

Building Type School	County Lane	
Street 88960 Territorial Hwy		
City Elmira	State OR	Zip 97437
Latitude 44.07233	Longitude 123.35454	
Tracking Code RVS in 2006	Inspection Date 7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Elmira Elementary School

### Final RVS Score

Final Type	Final Score
W2	0.5

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Elmira Elementary School

Lane\_sch44B

Enrollment 287	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1940	Est. Decade Built 1940
Total Area (square ft) 36486	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Vertical Irregularity Primary		SE Vertical Irregularity Primary	
		SW Plan Irregularity Primary	
			
W Other shows the connection between B and C.		NW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Elmira Elementary School

Fern Ridge SD 28J

Lane\_sch44C

Building Type	County	
School	Lane	
Street		
88960 Territorial Hwy		
City	State	Zip
Elmira	OR	97437
Latitude	Longitude	
44.07256	123.35488	
Tracking Code	Inspection Date	
RVS in 2006	7/24/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Elmira Elementary School

### Final RVS Score

Final Type	Final Score
RM1	0.7

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Elmira Elementary School

Lane\_sch44C

Enrollment 287	Year Built (Field Verified) 1945	Year Built (Alt. Source) 1945	Est. Decade Built 1980
Total Area (square ft) 36486	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Plan Irregularity Primary		SE Plan Irregularity Primary	
		SW Plan Irregularity Primary	
		W Vertical Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries