

Malabon Elementary School

Bethel SD 52

Lane_sch59A

Building Type	County
School	Lane
Street	
1380 Taney St	
City	State Zip
Eugene	OR 97402
Latitude	Longitude
44.07675	123.16109
Tracking Code	Inspection Date
SER & RVS2006	7/31/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Malabon Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Malabon Elementary School

Lane_sch59A

Enrollment 295	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 27300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Elevation View		N Plan Irregularity Primary	
		W Vertical Irregularity Primary	
			
S Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Malabon Elementary School

Bethel SD 52

Lane_sch59B

Building Type	County	
School	Lane	
Street		
1380 Taney St		
City	State	Zip
Eugene	OR	97402
Latitude	Longitude	
44.07707	123.16164	
Tracking Code	Inspection Date	
SER & RVS2006	8/5/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Tertiary		0	0	0	0	0	0	0	0	0

Malabon Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Malabon Elementary School

Lane_sch59B

Enrollment 295	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1953	Est. Decade Built 1950
Total Area (square ft) 27300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		None None None	
Falling Hazards		Poor Conditions	
None None None		None None None	
			
W Primary Structural Type and secondary structural type	NW Primary Structural Type	NW Plan Irregularity Primary	
			
N Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Malabon Elementary School

Bethel SD 52

Lane_sch59C

Building Type	County
School	Lane
Street	
1380 Taney St	
City	State Zip
Eugene	OR 97402
Latitude	Longitude
44.07655	123.16211
Tracking Code	Inspection Date
SER & RVS2006	8/5/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Tertiary		0	0	0	0	0	0	0	0	0

Malabon Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Malabon Elementary School

Lane_sch59C

Enrollment 295	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 27300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change Vertical Change in Structural Type (Soft over Stiff) None	
Falling Hazards None None None		Poor Conditions None None None	
			
E Primary Structural Type and secondary structural type. W2 on the upper level and RM1 on the lower level		SE Primary Structural Type and secondary structural type.	
		W Elevation View 	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Malabon Elementary School

Bethel SD 52

Lane_sch59D

Building Type	County
School	Lane
Street	
1380 Taney St	
City	State Zip
Eugene	OR 97402
Latitude	Longitude
44.07654	123.16167
Tracking Code	Inspection Date
SER & RVS2006	8/5/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Tertiary		0	0	0	0	0	0	0	0	0

Malabon Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Malabon Elementary School

Lane_sch59D

Enrollment 295	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1953	Est. Decade Built 1950
Total Area (square ft) 27300	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Elevation View			