

Shasta Middle School

Lane_sch60A

Bethel SD 52

Building Type		County	
School		Lane	
Street			
4656 Barger Ave			
City	State	Zip	
Eugene	OR	97402	
Latitude		Longitude	
44.08383		123.17714	
Tracking Code		Inspection Date	
SER & RVS2006		7/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Shasta Middle School

Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
79506	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



E Primary Structural Type

Shasta Middle School

Lane_sch60B

Bethel SD 52

Building Type		County	
School		Lane	
Street			
4656 Barger Ave			
City	State	Zip	
Eugene	OR	97402	
Latitude		Longitude	
44.08366		123.17699	
Tracking Code		Inspection Date	
SER & RVS2006		7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary	W2	3.8	0	0	0	0	-0.4	0	0	3.4
Tertiary		0	0	0	0	0	0	0	0	0

Shasta Middle School

Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
79506	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



W Primary Structural Type
and secondary structural type.

Shasta Middle School

Lane_sch60C

Bethel SD 52

Building Type		County	
School		Lane	
Street			
4656 Barger Ave			
City	State	Zip	
Eugene	OR	97402	
Latitude		Longitude	
44.0832		123.177	
Tracking Code		Inspection Date	
SER & RVS2006		7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary	RM1	2.8	-1	0	0	0	-0.4	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Shasta Middle School

Final RVS Score

Final Type

Final Score

RM1

1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
79506	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SW Vertical Irregularity Primary

Shasta Middle School

Lane_sch60D

Bethel SD 52

Building Type		County	
School		Lane	
Street			
4656 Barger Ave			
City	State	Zip	
Eugene	OR	97402	
Latitude		Longitude	
44.08397		123.17761	
Tracking Code		Inspection Date	
SER & RVS2006		7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Shasta Middle School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1962	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
79506	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: T shaped	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Shasta Middle School

Lane_sch60E

Bethel SD 52

Building Type		County	
School		Lane	
Street			
4656 Barger Ave			
City	State	Zip	
Eugene	OR	97402	
Latitude		Longitude	
44.08324		123.17727	
Tracking Code		Inspection Date	
SER & RVS2006		7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Shasta Middle School

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
457		1962	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
79506	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L Shaped	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None