

Junction City SD 69

Lane_sch64A

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Junction City High School

Lane_sch64A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
630		1937	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
205500	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None


Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



N Falling Hazard



N Primary Structural Type



N Secondary Structural Type
brick hall walls



N Elevation View



NW Vertical Irregularity Primary



NW Secondary Structural Type



W Plan Irregularity Primary



SW Secondary Structural Type



S Elevation View

Junction City SD 69

A photograph of a large, modern, dark-colored building with a flat roof, situated behind a grassy field. The building has several large windows and a prominent entrance area. The sky is clear and blue.

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
630	1966	1937	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
205500	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



W Elevation View



N Primary Structural Type



SE Elevation View



SW Elevation View



W Primary Structural Type



NE Elevation View



Junction City SD 69

Lane_sch64C

A photograph of a school building with a chain-link fence in the foreground and a clear blue sky. The building is a long, single-story structure with a light-colored facade and a dark roof. There are several windows visible, some with white frames. A chain-link fence runs along the right side of the building, separating it from a grassy area. The sky is a clear, bright blue.

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
630	1966	1937	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
205500	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



SE Plan Irregularity Primary

E Elevation View
windows blocked in upgrade

E Plan Irregularity Secondary



Junction City SD 69

Lane_sch64D

Building Type	County	
School	Lane	
Street		
1136 W 6th St		
City	State	Zip
Junction City	OR	97448
Latitude	Longitude	
44.21712	123.20922	
Tracking Code	Inspection Date	
RVS in 2006	1/30/2007	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	0	0	-0.8	0	3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Junction City High School

Final RVS Score

Final Type


Final Score

W2

3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
630	1966	1937	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
205500	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



NE Elevation View



SW Elevation View



W Elevation View



Junction City SD 69

Lane_sch64E

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
630	1937	1937	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
205500	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Single Change
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



E Primary Structural Type

E Field Verified Year Built
1937SE Plan Irregularity Secondary
crack in veneerS Elevation View
1996 on left

SW Vertical Irregularity Secondary



W Elevation View

SW General Site
metals bldgNW Elevation View
metals bldgNW Elevation View
1996 on left