

# Oakridge High School

Oakridge SD 76

Lane\_sch67A

Building Type	County
School	Lane
Street	
47997 W 1st St.	
City	State Zip
Oakridge	OR 97463
Latitude	Longitude
43.74879	122.46882
Tracking Code	Inspection Date
RVS in 2006	7/20/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3
Secondary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Oakridge High School

## Final RVS Score

Final Type	Final Score
RM1	0.3

## FEMA-154 Collapse Potential

High (>10%)





OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Oakridge High School

Lane\_sch67A

Enrollment 252	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1957	Est. Decade Built 1970
Total Area (square ft) 104546	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Vertical Irregularity Primary and reentrant corner	NE Vertical Irregularity Primary and reentrant corner	NE Vertical Irregularity Primary	
			
NE Plan Irregularity Primary	E General Site	SE Plan Irregularity Primary	
			
S Primary Structural Type brickwork behind façade	S General Site	SE Primary Structural Type left is inside gym entrance, center is the door I am holding open, right is the façade outside that is covering the rm1.	



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries