

Village School

Eugene SD 4J

Lane_sch82A

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Lane | |
| Street 2855 Lincoln St | | |
| City Eugene | State OR | Zip 97405 |
| Latitude 44.0275 | Longitude 123.09602 | |
| Tracking Code RVS in 2006 | Inspection Date 7/21/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Village School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 1.3 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Village School

Lane_sch82A

| | | | |
|--|-----------------------------|--|---------------------------|
| Enrollment 198 | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built 1950 |
| Total Area (square ft) | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None | | Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  W General Site | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Village School

Eugene SD 4J

Lane_sch82B

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type School | County Lane | |
| Street 2855 Lincoln St | | |
| City Eugene | State OR | Zip 97405 |
| Latitude 44.02698 | Longitude 123.09581 | |
| Tracking Code RVS in 2006 | Inspection Date 8/2/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Village School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 1.3 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Village School

Lane_sch82B

| | | | |
|--|-----------------------------|---|---------------------------|
| Enrollment 198 | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built 1950 |
| Total Area (square ft) | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners: Other None None | | Vertical Irregularities Steps in Elevation View: Single Change None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | | | |
| NW Vertical Irregularity Primary | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Village School

Eugene SD 4J

Lane_sch82C

| | | |
|-----------------|-----------------|-------|
| Building Type | County | |
| School | Lane | |
| Street | | |
| 2855 Lincoln St | | |
| City | State | Zip |
| Eugene | OR | 97405 |
| Latitude | Longitude | |
| 44.0273 | 123.09656 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 7/21/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Secondary | W2 | 3.8 | -2 | -0.5 | 0 | 0 | 0 | 0 | 0 | 1.3 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Village School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 1.3 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Village School

Lane_sch82C

| | | | |
|--|-----------------------------|---|---------------------------|
| Enrollment 198 | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built 1950 |
| Total Area (square ft) | Number of Stories 2 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None | | Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: Single Change (Adjacent Building/Entity) None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | |  | |
| W Vertical Irregularity Primary reentrant corner | | W General Site | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries