

Ridgeline Montessori

Eugene SD 4J

Lane_sch91A

Building Type	County	
School	Lane	
Street		
2855 Lincoln St		
City	State	Zip
Eugene	OR	97402
Latitude	Longitude	
44.0275	123.09602	
Tracking Code	Inspection Date	
RVS in 2006	8/2/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Ridgeline Montessori

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment 226	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 1	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 <p>W General Site also shows small retaining walls.</p>			



Ridgeline Montessori

Eugene SD 4J

Lane_sch91B

Building Type	County	
School	Lane	
Street		
2855 Lincoln St		
City	State	Zip
Eugene	OR	97402
Latitude	Longitude	
44.02698	123.09581	
Tracking Code	Inspection Date	
RVS in 2006	8/2/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Ridgeline Montessori

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment 226	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 1	Number of Stories 1	Basement No	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 NW General Site			



Ridgeline Montessori

Eugene SD 4J

Lane_sch91C

Building Type	County	
School	Lane	
Street		
2855 Lincoln St		
City	State	Zip
Eugene	OR	97402
Latitude	Longitude	
44.0273	123.09656	
Tracking Code	Inspection Date	
RVS in 2006	8/2/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0


Ridgeline Montessori

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment 226	Year Built (Field Verified) 	Year Built (Alt. Source) 	Est. Decade Built 1950
Total Area (square ft) 	Number of Stories 2	Basement No	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Building On Hill or Sloped Site Steps in Elevation View: Single Change (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary Sloped site.		W General Site	

