

# North Lincoln Fire & Rescue

Linc\_fir01A

North Lincoln Fire & Rescue

Building Type Fire - RFPD	County Lincoln	
Street 2525 NW Hwy 101		
City Lincoln City	State OR	Zip 97367
Latitude 44.98366	Longitude 124.00765	
Tracking Code RVS in 2006	Inspection Date 8/8/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

North Lincoln Fire & Rescue

### Final RVS Score

Final Type	Final Score
RM1	1.3

### FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# North Lincoln Fire & Rescue

Linc\_fir01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1991	1991	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE Vertical Irregularity Primary reentrant corner also		S Field Verified Year Built	
		NW Secondary Structural Type	
			
NW Plan Irregularity Primary		SW Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries