

North Lincoln Fire & Rescue - Otis Fire Dept.

Linc_fir02A

North Lincoln Fire & Rescue

Building Type	County	
Fire - RFPD	Lincoln	
Street		
381 Old Scenic Hwy		
City	State	Zip
Otis	OR	97368
Latitude	Longitude	
45.02448	123.94713	
Tracking Code	Inspection Date	
RVS in 2006	8/8/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	0	0	0	0	3.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Lincoln Fire & Rescue - Otis Fire Dept.

Final RVS Score

Final Type	Final Score
W1	3.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

North Lincoln Fire & Rescue - Otis Fire Dept.

Linc_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	Yes	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		None	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
NW Primary Structural Type		SE Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries