

Yachats RFPD & S. Lincoln Ambulance Service

Yachats RFPD

Linc_fir08A

Building Type Fire - RFPD	County Lincoln	
Street 217 W 2nd St		
City Yachats	State OR	Zip 97498
Latitude 44.31114	Longitude 124.10472	
Tracking Code RVS in 2006	Inspection Date 8/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Yachats RFPD & S. Lincoln Ambulance Service

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Yachats RFPD & S. Lincoln Ambulance Service

Linc_fir08A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: T shaped (Adjacent Build/Entity)		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
S Vertical Irregularity Secondary out-of-plane offset also		NW Plan Irregularity Tertiary step in elevation also	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yachats RFPD & S. Lincoln Ambulance Service

Yachats RFPD

Linc_fir08B

Building Type Fire - RFPD	County Lincoln	
Street 217 W 2nd St		
City Yachats	State OR	Zip 97498
Latitude 44.31114	Longitude 124.10484	
Tracking Code RVS in 2006	Inspection Date 8/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Yachats RFPD & S. Lincoln Ambulance Service

Final RVS Score

Final Type	Final Score
W1	1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yachats RFPD & S. Lincoln Ambulance Service

Linc_fir08B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yachats RFPD & S. Lincoln Ambulance Service

Linc_fir08C

Yachats RFPD

Building Type	County	
Fire - RFPD	Lincoln	
Street		
217 W 2nd St		
City	State	Zip
Yachats	OR	97498
Latitude	Longitude	
44.31121	124.10467	
Tracking Code	Inspection Date	
RVS in 2006	8/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Yachats RFPD & S. Lincoln Ambulance Service

Final RVS Score

Final Type	Final Score
W1	3.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yachats RFPD & S. Lincoln Ambulance Service

Linc_fir08C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: T shaped		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	