

Central Oregon Coast F&R Dist

Linc_fir11A

Central Oregon Coast RFPD

Building Type		County	
Fire - RFPD		Lincoln	
Street			
145 Alsea Hwy			
City	State	Zip	
Waldport	OR	97394	
Latitude		Longitude	
44.42718		124.06258	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Central Oregon Coast F&R Dist

Final RVS Score

Final Type

Final Score

--	--

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1995	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions