

# North Lincoln Fire & Rescue

Linc\_fir12A

North Lincoln Fire & Rescue

Building Type Fire - RFPD	County Lincoln	
Street 914 SW 4th St		
City Lincoln City	State OR	Zip 97372
Latitude 44.96406	Longitude 124.01821	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Lincoln Fire & Rescue

## Final RVS Score

Final Type	Final Score
RM1	2.8

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Lincoln Fire & Rescue

Linc\_fir12A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		Cracks	
None		None	
None		None	
			
N Poor Condition cracks		SW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries