

# North Lincoln Fire & Rescue - Kernville Station

Linc\_fir14A

North Lincoln Fire & Rescue

Building Type	County	
Fire - RFPD	Lincoln	
Street		
37625 Siletz River Hwy		
City	State	Zip
Lincoln City	OR	97367
Latitude	Longitude	
44.88456	123.94466	
Tracking Code	Inspection Date	
RVS in 2006	8/10/2006	



Seismicity Zone: Very High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Lincoln Fire & Rescue - Kernville Station

## Final RVS Score

Final Type	Final Score
S3	2.7

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# North Lincoln Fire & Rescue - Kernville Station

Linc\_fir14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE	Plan Irregularity Secondary	W	Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries