

Seal Rock RFPD - Bayshore Station

Linc_fir20A

Seal Rock RFPD

Building Type	County	
Fire - RFPD	Lincoln	
Street		
2009 NW Hilton Dr		
City	State	Zip
Seal Rock	OR	97376
Latitude	Longitude	
44.44088	124.07517	
Tracking Code	Inspection Date	
RVS in 2006	8/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Seal Rock RFPD - Bayshore Station

Final RVS Score

Final Type	Final Score
W1	6.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Seal Rock RFPD - Bayshore Station

Linc_fir20A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2336	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Steps in Elevation View: Single Change	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE	Vertical Irregularity Primary	E	Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries