

Samaritan North Lincoln Hospital - Lincoln City

Samaritan Health Services NFP

Linc_hos02A

Building Type	County
Hospital	Lincoln
Street	
3043 NE 28th St	
City	State Zip
Lincoln City	OR 97367
Latitude	Longitude
44.98604	123.99507
Tracking Code	Inspection Date
RVS in 2006	8/10/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Samaritan North Lincoln Hospital - Lincoln City

Final RVS Score

Final Type	Final Score
W2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Samaritan North Lincoln Hospital - Lincoln City

Linc_hos02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1980	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
10234	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
 A photograph of the Samaritan North Lincoln Hospital building. The building is a single-story structure with a dark, horizontal-panelled facade. The words "SAMARITAN NORTH LINCOLN HOSPITAL" are printed in white capital letters on the upper left portion of the building. There is a small entrance area with a glass door and some shrubs in front. A dark car is parked in the foreground on the left side of the building. The sky is clear and blue.			
N Vertical Irregularity Primary reentrant corners also			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries