

Yaquina View Elementary School

Lincoln County SD

Linc_sch08A

Building Type	County
School	Lincoln
Street	
351 SE Harney St	
City	State Zip
Newport	OR 97365
Latitude	Longitude
44.63361	124.04154
Tracking Code	Inspection Date
RVS in 2006	8/14/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Yaquina View Elementary School

Final RVS Score

Final Type	Final Score
C2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Yaquina View Elementary School

Linc_sch08A

Enrollment 300	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1960
Total Area (square ft) 46357	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent)	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: General		None	
None		None	
			
NW Falling Hazard covered walkway at entrance	NW General Site	W Plan Irregularity Primary steps in elevation also	
			
S General Site	N Falling Hazard	NE General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yaquina View Elementary School

Lincoln County SD

Linc_sch08B

Building Type School	County Lincoln	
Street 351 SE Harney St		
City Newport	State OR	Zip 97365
Latitude 44.63344	Longitude 124.04139	
Tracking Code RVS in 2006	Inspection Date 8/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Yaquina View Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Yaquina View Elementary School

Linc_sch08B

Enrollment 300	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1970
Total Area (square ft) 46357	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE General Site		E Primary Structural Type	
			
		NE Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yaquina View Elementary School

Lincoln County SD

Linc_sch08C

Building Type	County	
School	Lincoln	
Street		
351 SE Harney St		
City	State	Zip
Newport	OR	97365
Latitude	Longitude	
44.63313	124.04136	
Tracking Code	Inspection Date	
RVS in 2006	8/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Yaquina View Elementary School

Final RVS Score

Final Type

RM1

Final Score

1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Yaquina View Elementary School

Linc_sch08C

Enrollment 300	Year Built (Field Verified) 1961	Year Built (Alt. Source) 1961	Est. Decade Built 1990
Total Area (square ft) 46357	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity)		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Out of Plane Lateral-Force-Resistance Elements None		None	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	