

Newport High School - East

Lincoln County SD

Linc_sch09A

Building Type	County	
School	Lincoln	
Street		
322 NE Eads St		
City	State	Zip
Newport	OR	97365
Latitude	Longitude	
44.63881	124.04608	
Tracking Code	Inspection Date	
RVS in 2006	8/14/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary	S3	3.2	0	-0.5	0	0	0	0	0	2.7

Newport High School - East

Final RVS Score

Final Type	Final Score
C2	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Newport High School - East

Linc_sch09A

Enrollment 747	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1950
Total Area (square ft) 162742	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
 W General Site Boone Center - 1994 Addition		 SW General Site	
 W Primary Structural Type		 NW Plan Irregularity Primary step in elevation also	
 NE Primary Structural Type secondary and tertiary structural types also			

Newport High School - East

Lincoln County SD

Linc_sch09B

Building Type	County
School	Lincoln
Street	
322 NE Eads St	
City	State Zip
Newport	OR 97365
Latitude	Longitude
44.63899	124.04532
Tracking Code	Inspection Date
RVS in 2006	8/14/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Newport High School - East

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Newport High School - East

Linc_sch09B

Enrollment 747	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1980
Total Area (square ft) 162742	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

Newport High School - East

Lincoln County SD

Linc_sch09C

Building Type	County
School	Lincoln
Street	
322 NE Eads St	
City	State Zip
Newport	OR 97365
Latitude	Longitude
44.63839	124.04573
Tracking Code	Inspection Date
RVS in 2006	8/14/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Tertiary		0	0	0	0	0	0	0	0	0

Newport High School - East

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Newport High School - East

Linc_sch09C

Enrollment 747	Year Built (Field Verified) 1951	Year Built (Alt. Source) 1951	Est. Decade Built 1980
Total Area (square ft) 162742	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



S Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries