

Toledo High School

Lincoln County SD

Linc_sch11A

Building Type	County
School	Lincoln
Street	
1800 NE Sturdevant Rd	
City	State Zip
Toledo	OR 97391
Latitude	Longitude
44.63359	123.92142
Tracking Code	Inspection Date
RVS in 2006	8/12/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Toledo High School

Final RVS Score

Final Type	Final Score
PC1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Toledo High School

Linc_sch11A

Enrollment 410	Year Built (Field Verified) 1997	Year Built (Alt. Source) 1955	Est. Decade Built 1990
Total Area (square ft) 80744	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site	
Falling Hazards None None None		Poor Conditions None None None	
			
SE Vertical Irregularity Secondary reentrant corner also		S Field Verified Year Built	



OregonGeology


Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
 Oregon Department of Geology and Mineral Industries

Toledo High School

Lincoln County SD

Linc_sch11B

Building Type School	County Lincoln	
Street 1800 NE Sturdevant Rd		
City Toledo	State OR	Zip 97391
Latitude 44.63368	Longitude 123.92186	
Tracking Code RVS in 2006	Inspection Date 8/12/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Toledo High School

Final RVS Score

Final Type	Final Score
C2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Toledo High School

Linc_sch11B

Enrollment 410	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1950
Total Area (square ft) 80744	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
 W Number of Stories		 W Primary Structural Type	
		 W Field Verified Year Built 1955	
 N Vertical Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Toledo High School

Lincoln County SD

Linc_sch11C

Building Type	County
School	Lincoln
Street	
1800 NE Sturdevant Rd	
City	State Zip
Toledo	OR 97391
Latitude	Longitude
44.63381	123.92089
Tracking Code	Inspection Date
RVS in 2006	8/12/2006



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9

Toledo High School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Toledo High School

Linc_sch11C

Enrollment 410	Year Built (Field Verified) 1955	Year Built (Alt. Source) 1955	Est. Decade Built 1950
Total Area (square ft) 80744	Number of Stories 2	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) Building On Hill or Sloped Site	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Vertical Irregularity Primary reentrant corner also		SE Secondary Structural Type tertiary structural type and reentrant corner also	
		S Number of Stories built on slope also	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
 Oregon Department of Geology and Mineral Industries