

Waldport High School

Lincoln County SD

Linc_sch12A

Building Type School	County Lincoln	
Street 320 Lower Crestline Dr		
City Waldport	State OR	Zip 97394
Latitude 44.42782	Longitude 124.0591	
Tracking Code RVS in 2006	Inspection Date 8/7/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Waldport High School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Waldport High School

Linc_sch12A

Enrollment 291	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 47063	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: T shaped		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Torsion: Eccentric Stiffness		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Plan Irregularity Primary		E Vertical Irregularity Secondary reentrant corner also	
		SW General Site	
			
NE Plan Irregularity Tertiary actually 4th level of plan irregularity - ran out of labels. This is a non-parallel LFR system.		W Plan Irregularity Tertiary eccentric stiffness: torsion	
			
		NE General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries