

Eddyville Charter School

Lincoln County SD

Linc_sch15A

Building Type	County	
School	Lincoln	
Street		
57 Eddyville School Rd		
City	State	Zip
Eddyville	OR	97343
Latitude	Longitude	
44.63405	123.77748	
Tracking Code	Inspection Date	
RVS in 2006	8/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Eddyville Charter School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Eddyville Charter School

Linc_sch15A

Enrollment 319	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1940
Total Area (square ft) 43016	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		Cripple Walls	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Vertical Irregularity Tertiary		SE Vertical Irregularity Secondary reentrant corners also. Partial basement?	
		SE Vertical Irregularity Primary reentrant corners also	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Eddyville Charter School

Lincoln County SD

Linc_sch15B

Building Type School	County Lincoln	
Street 57 Eddyville School Rd		
City Eddyville	State OR	Zip 97343
Latitude 44.6342	Longitude 123.77802	
Tracking Code RVS in 2006	Inspection Date 8/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Eddyville Charter School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Eddyville Charter School

Linc_sch15B

Enrollment 319	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1960
Total Area (square ft) 43016	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
SW Plan Irregularity Primary step in elevation also		S Primary Structural Type secondary structural type also	N Plan Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Eddyville Charter School

Lincoln County SD

Linc_sch15C

Building Type	County	
School	Lincoln	
Street		
57 Eddyville School Rd		
City	State	Zip
Eddyville	OR	97343
Latitude	Longitude	
44.63437	123.77863	
Tracking Code	Inspection Date	
RVS in 2006	8/11/2006	



Seismicity Zone: Very High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	0	2.4	-0.4	0	0	5.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Eddyville Charter School

Final RVS Score

Final Type	Final Score
W2	5.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Eddyville Charter School

Linc_sch15C

Enrollment 319	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1980
Total Area (square ft) 43016	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 W General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries