

# College Center

Linn-Benton CC

Linn\_coc02A

Building Type	County	
Community_College	Linn	
Street		
6500 SW Pacific Blvd		
City	State	Zip
Albany	OR	97321
Latitude	Longitude	
44.58689	123.1124	
Tracking Code	Inspection Date	
Miller 2004-05	5/13/2004	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.5	-1.5	-0.5	0	0	0	-0.6	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


College Center

## Final RVS Score

Final Type	Final Score
C1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# College Center

Linn\_coc02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1973	1973	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
54591	2	No	No
Plan Irregularities		Vertical Irregularities	
Yes: Unknown		None	
Falling Hazards		Poor Conditions	
None			
None			
None			
			
S	General Site	S	General Site
			
S	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries